

**No. 10 Reel Ratchet Pawl and
Bevel Gear Replacement Sets****SERVICE BULLETIN
NUMBER SD-179**

Users ordering pawl replacement parts for Number 10 reel ratchet assemblies should be informed of the following:


A design change to both the ratchet pawl tooth and mating bevel gear cavity has been made.

▲ CAUTION


DO NOT use the new pawl with obsolete design bevel gears.

When replacing either of these parts, be certain that only newly designed parts are used in combination with one another.

Proper identification of these parts are as illustrated and labeled below.



OBSOLETE
PAWL & BEVEL GEAR



NEW
PAWL & BEVEL GEAR

LITTELL INTERNATIONAL, INC.
145 SWIFT ROAD, ADDISON, ILLINOIS 60101-1407, U.S.A.
AREA CODE: (630) 916-6662 LITTELL TELEFAX: (630) 916-6663
SERVICE DEPARTMENT TELEFAX: (630) 916-6664